

## MONUMENT RECORD


STATE OF INDIANA - COUNTY OF MONROE

SECTION 10, 11, 14, 15 TOWNSHIP 7 NORTH, RANGE 1 EAST

## MONUMENT DESCRIPTION &amp; REMARKS

THE CORNER POINT IS UNDER WATER, NO MONUMENT WAS SET.THE CALCULATED CORNER POINT IS AT THE JUNCTION OF THE E-WFENCE LINE, N-S ROAD, AND NW CORNER OF THE OLD SCHOOL HOUSE LOT.


## RECOVERY TIE DRAWING



(●) AT CORNER



NOT TO SCALE



STATE OF INDIANA

COUNTY OF MONROE

I, EDMUND O. FARKAS HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL THIS 30 DAY OF APRIL, 1981 A.D.

SPACE  
RESERVED  
FOR  
RECORDING  
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. \_\_\_\_\_

OR \_\_\_\_\_

UNITED STATES GOVERNMENT AGENCY

TOWNSHIP:

POLK

CORNER I.D.

Q - 9

TITLE

RECORDED  
A.M. \_\_\_\_\_ P.M. 1:39 ✓

POLK-Q09

MAR 18 1985

168701

✓ *Virginia H. Anderson*  
RECORDER MONROE CO., IND ✓  
R9-7150-15 (5/64)

BOOK 155 PAGE 513

CERTIFIED LAND CORNER RESTORATION

State of Indiana }  
County of Monroe } ss.

I Edmund O. Farkas, do hereby certify that on the 30th day of April, 1981,  
I found evidence of the reestablished the section corner of Sections 10, 11, 14 & 15  
Township 7 North, Range 1 East, Second Principal Meridian, as described  
hereon; and that from this evidence I established a new monument and accessories as described hereon to per-  
petuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:

Original monument was a wood post set  
in 1814. Original Bearing Trees:

No evidence of subsequent  
restoration.



|           |          |
|-----------|----------|
| Hackberry | Walnut   |
| 15"       | 4"       |
| S40W      | S47E     |
| 26 Links  | 11 Links |

Description of corner evidence found:

This corner is under water, Lake Monroe Reservoir, and no evidence was found of a corner monument or accessories. Old fence lines east and west from corner location and an old county road north and south. The northwest corner of section 14 had a .25 acre school lot prior to the creation of the reservoir. The south, east, and part of the north lines are visible yet and from them the NW corner of the lot was calculated. Presumably the section corner was at or nearly at that lot corner. This calculated location also coincided with the road and E-W fence line, too.


Description of ~~monument~~ and accessories I established to perpetuate the original location of this corner:

With the corner point under water, no monument was set. The calculated corner point is at the junction of the E-W fence line, N-S road, and NW corner of the old school house lot. This information was also supported by the Corps of Engineers survey of the reservoir prior to it being flooded. As accessories to the corner, two Corps of Engineers monuments, marked as shown, were used. The monuments are 6" in diameter, concrete posts with 3" brass caps.



Monument  
6"  
S89° 56'W  
432.23 FT.

Monument  
6"  
S80° 32'W  
445.36 FT.



● = Corner monument restored  
□ =

Resident witnesses Kenneth W. Anderson

Dated at Bedford Indiana, this 12th day of June 1981.

Signature Edmund O. Farkas Title Land Surveyor  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Surveyors Registration No. S0114

Office of \_\_\_\_\_ County of \_\_\_\_\_  
I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_ 19\_\_\_\_, and was filed in Book No. \_\_\_\_\_ Page No. \_\_\_\_\_ of County Records.

Signature \_\_\_\_\_ Title \_\_\_\_\_

Township 7 North, Range 1 East, Section 10, 11  
This instrument was prepared 15, 14, Index No. J-17, Page No. \_\_\_\_\_

Index No. J-17  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)  
GPO 806-924T. 7N R. 1E 2nd Mer. N.F. HOOSIER County MONROE State IND  
SECTION Corner common to sections 10, 11, 14 and 15

## EXISTING SURVEYS

## Original Government Survey

Year surveyed 1811  
Original monument WOOD POST  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species HACK WAL  
Diameter 15" 4"  
Bearing S40W S47E  
Distance 26 LKS 11 LKS

## Subsequent Corner Restoration

Year surveyed 1861 By E. BUSKIRK  
Where filed or recorded MON CO. ENG. OFFICE  
Monument (Original, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species B. OAK R. OAK  
Diameter 12" 25"  
Bearing N80°W N11E  
Distance 21 LKS. 14 LKS.

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

## Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_


## Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Under Lake

## Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

At time of search:

1. Did you have the record description?  
Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?  
Pacing, chaining, photos, maps,  
etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do  
rec \_\_\_\_\_

5. Sign \_\_\_\_\_

# Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
Object \_\_\_\_\_  
Record distance \_\_\_\_\_  
Measured distance \_\_\_\_\_

## Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

## Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Stone 8x8x6

prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Which is filed at \_\_\_\_\_

4 W. MOHNS & SONS